

sj
B.R.

LONDON MIDLAND OPERATING AREA.
(Western Division)

ERO.46857

PASSENGER ENGINE WORKINGS - COMMENCING JUNE 18th 1951.

ENGINE & MEN'S WORKINGS.

HEATON MERSEY : SHEET 2.

ONE CLASS 3 TANK (STD 2-6-2)

Book	Book	HM
<u>On</u>	<u>Off</u>	
am	am	
5.47	11.30	5.43
5.34	S.H.	

Turn 5.

SX		6.19am	S.H.		
SX	L.E.	6.32	Shed	Cheadle Heath	6.46am
SX	Pass.	7.10	Cheadle Heath	Manchester C.	7.32
SX	Pass.	8.15	Manchester C.	Cheadle Heath	8.37
SX	L.E.	-	Cheadle Heath	Shed	8.52
SX			COAL ENGINE		
SX			RELIEF on Shed 11.20am for 11.20am		
			L.E. to Cheadle Heath by Turn 6.		

Turn 6.

a.m.	p.m.
11.10	6.34 7.24

SX			RELIEVE Engine off 8.15am from		
			Manchester Turn 5 on on Shed at 11.20am		
SX	L.E.	11.20am	Shed	Cheadle Heath	11.34am
SX	Pass	1. 2pm	Cheadle Heath	Manchester C.	1.24
SX	E.S.	1.30	Manchester C.	Cornbrook C.S.	1.35
SX	L.E.	3. 5	Cornbrook C.S.	Manchester	3. 8
SX	Pass	3.35	Manchester C.	Cheadle Heath	3.57
SX	Pass	4.32	Cheadle Heath	Manchester C.	4.56
SX	Pass	5.10	Manchester C.	Stockport T.D.	5.34
SX	L.E.	-	Stockport T.D.	Shed	5.49
SX			DISPOSE.		

Turn 7.

a.m.	p.m.
5.47	2. 3 8.16

SO	L.E.	6.32am	Shed	Cheadle Heath	6.46am
SO	Pass	7.10	Cheadle Heath	Manchester	7.32
SO	Pass	8.15	Manchester C.	Cheadle Heath	8.37
SO	Pass	12.25pm	Cheadle Heath	Manchester C.	12.47pm
SO	Pass	1.15	Manchester C.	Cheadle Heath	1.38
SO	L.E.	-	Cheadle Heath	Shed	1.53
SO			RELIEF on arrival.		

PASSENGER ENGINE WORKINGS - COMMENCING JUNE 18th, 1951

ENGINEMEN'S WORKINGS ONLY

HEATON MERSEY - SHEET 10

				Book	Book	
				<u>On</u>	<u>Off</u>	<u>H.M.</u>
				p.m.	a.m.	
<u>Turn 64</u>				6. 8	12. 3	5.55
SX		RELIEVE 4.10pm from Dery 17A Turn 138 at 6.38pm				
SX	Pass	6.39pm	Heaton M. Mancr. C.	7. 0pm	(17A/44)	
SX	L.E.	7.15	Mancr. C. Trafford P.Shed	7.26		
SX			COAL ENGINE			
SX	L.E.	9.41	T.Park Shed Mancr. C.	9.52		
SX	Pass	10.10	Mancr. C. Cheadle Heath	10.32		
SX	L.E.	11. 5	Cheadle Heath Stockport T.D.	11.23		
		RELIEF 11.23pm for Derby by 17A Turn 159				

Turns 65 to 79

NOT USED

Turn 80

a.m. p.m.
8.57 - -

SO		RELIEVE 5.45am from Desford, 17A Turn 202, 203 & 204 at 9.22am				
SO	Pass	9.24am	Cheadle Heath Blackpool (N)	11.15am	(17C/1)	
SO	As reqd	-	Blackpool (N) Belle Vue Shed	-		
SO	By bus	-	Belle Vue Shed	-		

Turn 81

August 4th to 25th, incl.

a.m. p.m.
9.37 4.56 7.19

SO		RELIEVE 8.40am from Sheffield 19A Turn 38 at 10. 2am				
SO	Pass	10. 7am	Cheadle Hth Blackpool (C)	12.19pm	(19A/9)	
SO	L.E.	-	Blackpool C. B'pool C. Shed	12.35		
SO			Walk to North Shed			
SO			Take to Fresh engine			
SO	L.E.	2.25pm	B'pool Shed Blackpool N.			
SO	Pass	2.45	Blackpool (N) Cheadle Heath	4.31	(19A/7) (28A/-)	
SO			RELIEF 4.31pm for Sheffield by 19A Turn 47			

bs.
B.R.

ERO.46857.

LONDON MIDLAND OPERATING AREA.
WESTERN DIVISION

FREIGHT ENGINE WORKINGS: COMMENCING JUNE 18th, 1951.

ENGINE & MEN'S WORKINGS.

HEATON MERSEY : SHEET 21.

ONE CLASS 8F (STD. 2-8-0).

Book Book
On. Off. H.M.
a.m. p.m.
5.35 1.32 7.57

Turn 138.

MO ENGINE PREPARED by Turn 393.
MO L.E. 5.50am Shed Cheadle Sdgs. -
MO T.F. 6.20 Cheadle Sdgs. Walton 9.32am
MO Eties. 10. 0 Walton Cheadle Sdgs. 12.22pm
MO L.E. - Cheadle Sdgs. Shed 12.32
MO DISPOSE.

Turn 139.

p.m. a.m.
6.54 2.50 7.56

D ENGINE PREPARED by Turn 434.
D L.E. 7. 9pm Shed Cheadle Hth. -
D EF (D) 7.39 Cheadle Hth. Hartford GP. 9.55pm
(6.10pm from Tunstead)
D L.E. 10.15 Hartford GP. Hartford 10.20
D Engine to turn round triangle
and take water.
D L.E. 11.50 Hartford Hartford GP. 11.55
MX & Eties. 12.50am Hartford GP. Cheadle H.S.Jn. 2.21am
Sun.
MX & Sun. RELIEF 2.25am for Gt. Rocks by
Turn 140.

Turn 140.

a.m. a.m.
2. 0 7.56 5.56 MX
2. 0 9.41 7.41 Sun

MX & Sun. RELIEVE 12.50am from Hartford,
Turn 139 at 2.25am.
MX & Eties. 2.32am Cheadle H.S.Jn. Gt. Rocks Jn. 3.55am
Sun.
MX & L.E. - Gt. Rocks Jn. Tunstead -
Sun.
MX Min. 5.23 Tunstead Cheadle Sdgs. 6.46
MX L.E. - Cheadle Sdgs. Shed 6.56
Sun E.F.(D) 7.20 Tunstead Cheadle Sdgs. 8.31
Sun L.E. - Cheadle Sdgs. Shed 8.41
MX & Sun. DISPOSE.

Turn 141.

ONE CLASS 8F (STD. 2-8-0).
TARGET 93.

a.m. p.m.
8.45 4.45 8. 0

D L.E. 9.45am Shed Cheadle Hth. 9.58am
SX Frt. 10.10 Cheadle Hth. Didsbury 11.28
SX Frt. 12.27pm Didsbury Cheadle Hth. 12.39pm
SX 12.40 Work trips as req'd 4.30
SO 10. 0am Work trips as req'd -
D RELIEF 4.30pm by Turn 142.

Turn 142.

TARGET 93.

p.m. nt.
4.15 12. 0 7.45

D RELIEVE Turn 141 at 4.30pm
D 4.30pm Work trips as required. 11. 0pm
D L.E. - Where required Shed -

Turns 143 to 144.

NOT USED.