

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY.

MIRFIELD - SHEET 1.

Turn 1.

ONE CLASS 4 TANK (STD 2-6-4)

	Shed	7. 3am	LE	SX	(41)
7.22am	Headfield Jn.	7.40	ES	SX	
7.43	Thornhill	7.55	Pass	SX	
8.25	Bradford		LE	SX	
	Broomfield Sdgs.		ES	SX	
	Bradford	9.15	Bank	SX	
9.20	Bowling Jn.		LE	SX	
	Broomfield Sdgs.		ES	SX	
	Bradford	11.18	LE	SX	
11.48	Shed				

	Shed	4.22pm	LE	SX	(43)
4.25pm	Mirfield	4.30	Vans	SX	
7.45	Congleton	9.40	Milk	SX	
12.37am	Mirfield			MX	

	Mirfield	3.46am	Assist (1)	SO	(40)
4. 9am	Halifax	4.30	LE	SO	
4.58	Huddersfield	6.23	Pass	SO	
7.22	Bradford	7.57	Pass	SO	
8.49	Huddersfield	8.57	ES	SO	(42)
9.52	Clayton West	12. Onn	Pass	SO	
12.34pm	Huddersfield	12.36pm	Pass	SO	
1. 3	Halifax	1.20	LE	SO	
1.41	Shed				

(1) 3.15am from Normanton.

	Shed	4.22pm	LE	SO	(43)
4.25pm	Mirfield	4.30	Vans	SO	
7.45	Congleton	9.40	Milk	SO	
12.37am	Mirfield			Sun	

	Shed	4.40pm	LE	Sun	(45)
4.45pm	Mirfield	5. 0	Vans	Sun	
7.45	Congleton	9.25	Milk	Sun	
12.37am	Mirfield			MO	

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY.

MIRFIELD - SHEET 2.

Turn 2.

ONE CLASS 4 TANK (STD 2-6-4)					
	Mirfield	1. 9am	Milk	D	(51)
2. 3am	Normanton			D	
	SHUNT (Pass)			D	
	Normanton	5.37	Pass	D	
6.38	Sowerby Bge.	7.29	Pass	SX	(52)
6.38	Sowerby Bge.	7.20	Pass	SO	(53)
8.26	Normanton	9. 0	LE	SX	(52)
8.15	Normanton	9. 0	LE	SO	(53)
9.13	Wakefield Shed			D	
	COAL				
	Wakefield Shed	10. 0	LE	SX	
10. 5	Wakefield			SX	
	SHUNT Pass to	12.30pm		SX	
	Wakefield	12.40pm	Pass	SX	
1.26pm	Bradford	2. 5	LE Cpld	SX	(54)
2.13	Low Moor	3. 3	Pass	SX	
3.10	Bradford	4.25	Pass	SX	
5.44	Holmfirth	6.25	LE	SX	
7.14	Shed				
	Wakefield Shed	10. 0am	LE	SO	(53)
10. 5am	Wakefield			SO	
	SHUNT Pass to	10.45am		SO	
	Wakefield	10.53	Pass	SO	
11.19	Barnsley	11.25	Pass	SO	
11.49	Wakefield	12.40pm	Pass	SO	
1.26pm	Bradford	2.55	Pass	SO	(55)
4.24	Penistone	5.15	Pass	SO	
6.58	Bradford	7.38	LE	SO	
8. 4	Shed				

Turns 3 to 7.

N O T U S E D

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY.

MIRFIELD - SHEET 3.

Turn 8.

ONE CLASS 4 TANK (STD 2-6-4)

	Shed	5. 0am	LE	MO	(46)
	Shed	4.20am	LE	MSX	
5.10am	Huddersfield			MO	
4.25	Mirfield			MSX	
	SHUNT (Pass)			MSX	
	Mirfield	5. 0	Pass	MSX	(47)
5.11	Huddersfield	5.50	Pass	SX	
6.18	Penistone	6.48	Pass	SX	
7.22	Huddersfield	7.35	Pass	SX	
8.21	Bradford	8.45	LE	SX	
9.25	Shed			SX	
	Mirfield	5.50pm	Pass	SX	(49)
6.48pm	Penistone	7. 5	Pass	SX	
7.41	Huddersfield	10.15	Pass	SX	
10.50	Penistone	11. 7	Pass	SX	
11.37	Huddersfield	11.45	ES	S X	
11.57	Mirfield				
	Shed	4.20am	LE	SO	(62)
	SHUNT (Pass) to	4.45		SO	
	Mirfield	5. 0	Pass	SO	
5.11am	Huddersfield	5.50	Pass	SO	
6.18	Penistone	6.48	Pass	SO	
7.22	Huddersfield	7.42	Pass	SO	
8.12	Halifax	8.50	LE	SO	
9.12	Shed				
	Shed	2.50pm	LE	SO	(50)
2.57pm	Headfield Jn.	3.20	ES	SO	
3.28	Mirfield	3.50	LE	SO	
4. 0	Huddersfield	4.31	Pass	SO	
4.51	Marsden	5.10	ES	SO	
5.24	Huddersfield	5.29	Pcls	SO	
6.15	Bradford	7.34	Pass	SO	
8.41	Huddersfield	9.35	Assist	SO	
9.58	Halifax	10. 0	LE	SO	
10.28	Shed				

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY.

MIRFIELD - SHEET 4.

Turn 9.

ONE CLASS 4 TANK (STD 2-6-4)

	Mirfield	6. 0am	ES	SX	(57)
6. 9am	Headfield Jn.	7. 0	LE	S X	
7. 8	Thornhill	7.34	Pass	SX	
8. 2	Bradford	8.45	LE Cpld	SX	
9.25	Mirfield			SX	
	WORK AS REQUIRED			SX	
	Mirfield		LE	SX	
	Headfield Jn.	10.50	ES	SX	
11. 0	Mirfield				
	Shed	1.58pm	LE	SX	
2. 9pm	Headfield Jn.				
	SHUNT C. & W. SHOPS TO	2.45		SX	(48)
	Headfield Jn.	3.13	ES	SX	
3.32	Mirfield				
	SHUNT (Pass) to	4.45pm		SX	
	Mirfield	5.20	Pass	SX	
6. 9	Clayton West	6.37	Pass	SX	
7.25	Mirfield				
	Mirfield	6. 0am	ES	SO	(60)
6. 9am	Headfield Jn.	7. 0	LE	SO	
7. 8	Thornhill	7.34	Pass	SO	
8. 2	Bradford	8.25	ES	SO	
8.34	Low Moor	8.55	LE	SO	
9.17	Mirfield				
	SHUNT (Pass) to	11.30		SO	
	Mirfield	11.38	LE	SO	
11.48	Huddersfield	12.23pm	Pass	SO	
12.57pm	Clayton West	1.10	Pass	SO	
1.43	Huddersfield	1.53	LE	SO	
2. 3	Shed				
	Mirfield	5.20pm	Pass	SO	
6. 9pm	Clayton West	6.37	Pass	SO	(61)
7.25	Mirfield	7.29	ES	SO	
7.37	Headfield Jn.	7.50	LE	SO	
	Huddersfield	9.18	Pass	SO	
9.52	Clayton West	10.15	Pass	SO	
10.48	Huddersfield	11. 0	LE	SO	
11.10	Mirfield				

Turns 10 to 15.

N O T U S E D

MIRFIELD LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCR.
SHEET 75."

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE AND MEN'S WORKINGS. MIRFIELD - SHEET 5.

<u>ONE CLASS 4 TANK (STD 2-6-4)</u>				<u>Book</u>	<u>Book</u>	
				<u>On</u>	<u>Off</u>	<u>H. M.</u>
				a.m.	a.m.	
<u>Turn 16.</u>				3.10	11.37	8.27 SX
ENGINE PREPARED by Turn 46 (MO) 47 (MSX)						
	Shed	3.25am	LE	SX		
3.30am	Mirfield	3.46	Assist(1)	SX		
4. 9	Halifax	4.30	LE	SX		
4.58	Huddersfield	6.23	Pass	SX		
7.22	Bradford	8.35	Pass	SX		
9.51	Penistone	10.30	Pass	SX		
11. 8	Mirfield			SX		
	RELIEF 11. 9am by Turn 17			SX		
	(1) 3.15am from Normanton					

				a.m.	p.m.		
<u>Turn 17.</u>				10.41	7.20	8.39	SX
RELIEVE Turn 16 at 11. 9am							
	Mirfield	11.10am	Pass	SX			
11.42am	Bradford	12. Onn	LE Cpld	SX			
12. 9pm	Low Moor			SX			
	RE-COAL			SX			
	Low Moor	12.30pm	LE Cpld(1)	SX			
12.38	Bradford	1.20	Pass	SX			
2.47	Penistone	3. 5	Pass	SX			
4.27	Bradford	5.30	Pass	SX			
6.20	Huddersfield	6.46	ES	SX			
6.56	Mirfield		LE	SX			
7. 5	Shed						
	(1) Coupled to 27A/82)						

Turn 18.

N O T U S E D

				a.m.	p.m.					
<u>Turn 19.</u>				11.30	6.36	7. 6	SO			
<u>PREPARE ENGINE FOR:</u>		<u>Turn No:</u>	<u>Leaves Shed:</u>							
Mirfield SHUNT		163	1.20pm 'S'							
	Shed	1. 0pm	LE	SO						
1.10pm	Headfield Jn.	1.37	ES	SO						
1.40	Thornhill	1.50	Pass	SO						
2. 4	Wakefield	3.27	Pass	SO						
3.53	Barnsley	4. 2	Pass	SO						
4.26	Wakefield	5. 0	ES (1)	SO						
5.46	Low Moor	6. 0	LE	SO						
6.21	Shed									
(1) 4.40pm Blackpool Carriages										
RUNS TO JUNE 27TH AND COMMENCING 12TH SEPTEMBER.										

Turns 20 to 39.

N O T U S E D

MIRFIELD LOCO' to acknowledge receipt

'P' MANCR. SHEET 76."

by wire to "DIVISIONAL

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINEMEN'S WORKINGS ONLY

MIRFIELD - SHEET 6.

					Book	Book		
					On	Off	H.	M.
					a.m.	a.m.		
Turn 40.					2.40	9.37	6.47	SO
	Shed	3.25am	LE	SO				
6.30am	Mirfield	3.46(1)	AssistSO	(1)				
4. 9	Halifax	4.30	LE	SO				
4.58	Huddersfield	6.23	Pass	SO				
7.22	Bradford	7.57	Pass	SO				
8.49	Huddersfield							
	RELIEF 8.50am by Turn 42			SO				
	Huddersfield	9. 0	AS Pass	SO				
9. 9	Mirfield		or as reqd.					
	(1) 3.15am from Normanton							

					a.m.	p.m.		
					5. 8	12. 3	6.55	SX
Turn 41.								
	Shed	6. 8am	LE	SX				
6.13am	Mirfield			(108)				
	RELIEF 6.26am by Turn 228			SX				
	TAKE TO ENGINE PREPARED by turn 52			SX				
	Shed	7. 3	LE	SX				
7.22am	Headfield Jn.	7.40	ES	SX				
7.43	Thornhill	7.55	Pass	SX				(1)
8.25	Bradford		LE	SX				
	Broomfield Sdgs.		ES(1)	SX				
	Bradford	9.15	Bank	SX				
9.20	Bowling Jn.		LE	SX				
	Broomfield Sdgs.		ES(2)	SX				
	Bradford	11.18	LE	SX				
11.48	Shed							
	(1) 9.15am Liverpool Carriages.							
	(2) 11.15am Liverpool Carriages.							

					a.m.	p.m.		
					7.51	1.56	6. 5	SO
Turn 42.								
	Mirfield	8.19am	As Pass	SO				
8.30am	Huddersfield							
	RELIEVE 7.57am from			SO				
	Bradford Turn 40 at	8.50am						
	Huddersfield	8.57	ES	SO				(1)
9.52	Clayton West	12. Onn	Pass	SO				
12.34pm	Huddersfield	12.36pm	Pass	SO				
1. 3	Halifax	1.20	LE	SO				
1.41	Shed							

					p.m.	a.m.		
					4. 7	1. 5	8.53	D
Turn 43.								
	ENGINE PREPARED by Turn 218 (SX) 53 (SO)							
	Shed	4.22pm	LE	D				(1)
4.25pm	Mirfield	4.30	Vans	D				
7.45	Congleton	9.40	Milk	D				
12.37am	Mirfield			D				
12.50	Shed							

Turn 44.
N O T U S E D

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINEMEN'S WORKINGS ONLY MIRFIELD - SHEET7.

	Book	Book	
	On	Off	H. M.
	p.m.	a.m.	
Turn 45	4.25	1.10	8.45 Sun

ENGINE PREPARED by Turn 275				
	Shed	4.40pm	LE	Sun (1)
4.45pm	Mirfield	5. 0	Vans	Sun
7.45	Congleton	9.25	Milk	Sun
12.37am	Mirfield	12.50am		MO
12.55	Shed			

Turn 46		a.m.	a.m.	
		3.30	9.40	6.10 MO
PREPARE ENGINE FOR: Turn No: Leaves Shed:				
	3.46am to Halifax	16	3.25am 'S'	MO
	Shed	5. 0am	LE	MO
5.10am	Huddersfield	5.50	Pass	MO (8)
6.18	Penistone	6.48	Pass	MO
7.22	Huddersfield	7.35	Pass	MO
8.21	Bradford	8.45(1)	LE Cpld	MO
9.25	Shed			
	(1) Coupled to Turn 57			

Turn 47		a.m.	a.m.	
		2.40	9.40	7. 0 MSX
PREPARE ENGINE FOR: Turn No: Leaves Shed				
	3.46am to Halifax	16	3.25am 'S'	
	Shed	4.20am	LE	MSX
4.25am	Mirfield			MSX
	SHUNT (Pass)			MSX
	Mirfield	5. 0	Pass	MSX (8)
5.11	Huddersfield	5.50	Pass	MSX
6.18	Penistone	6.48	Pass	MSX
7.22	Huddersfield	7.35	Pass	MSX
8.21	Bradford	8.45(1)	LE Cpld	MSX
9.25	Shed			MSX
	(1) Coupled to Turn 57.			

Turn 48		p.m.	p.m.	
		1.13	8.50	7.37 SX
	Shed	1.58pm	LE	SX
2. 9pm	Headfield Jn.			SX
	SHUNT C. & W. SHOPS to	2.45pm		SX
	Headfield Jn.	3.13	ES	SX (9)
3.32	Mirfield			SX
	SHUNT (Pass) to	4.45		SX
	Mirfield	5.20	Pass	SX
6. 9	Clayton West	6.37	Pass	SX
7.25	Mirfield		LE	SX
7.50	Shed			
PREPARE ENGINE FOR: Turn No: Leaves Shed:				
	1. 9am to Normanton	51	12.35am	(MX)

MIRFIELD LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCHESTER. SHEET 78".

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINEMEN'S WORKINGS ONLY MIRFIELD - SHEET 8.

					Book	Book						
					<u>On</u>	<u>Off</u>	<u>H.</u>	<u>M.</u>				
					p.m.	a.m.						
<u>Turn 49</u>					4.30	12.30	8. 0	SX				
	Shed	5.15pm	LE	SX	(8)							
5.20pm	Mirfield	5.50	Pass	SX								
6.48	Penistone	7. 5	Pass	SX								
7.41	Huddersfield	10.15	Pass	SX								
10.50	Penistone	11. 7	Pass	SX								
11.37	Huddersfield	11.45	ES	SX								
11.57	Mirfield		LE	SX								
12.15am	Shed											
					p.m.	p.m.						
<u>Turn 50</u>					2.35	10.43	8. 8	SO				
	ENGINE PREPARED by Turn 53											
	Shed	2.50pm	LE	SO	(8)							
2.57pm	Headfield Jn.	3.20(1)	ES	SO								
3.28	Mirfield	3.50	LE	SO								
4. 0	Huddersfield	4.31	Pass	SO								
4.51	Marsden	5.10	ES	SO								
5.24	Huddersfield	5.29	Pass	SO								
6.15	Bradford	7.34	Pass	SO								
8.41	Huddersfield	9.35	Asst	SO								
9.58	Halifax	10. 0	LE	SO								
10.28	Shed											
	(1)	3.58pm Holmfirth and 5.20pm Clayton West Carriages.										
					a.m.	a.m.						
					12. 5	8.21	8.16	MO				
					12.20	8.21	8. 1	MSX				
<u>Turn 51</u>					12.20	8.11	7.51	SO				
	Shed	12.50am	LE	MO								
12.55am	Mirfield											
	ENGINE PREPARED by Turn 48			MX								
	Shed	12.35am	LE	MX	(2)							
12.40am	Mirfield	1. 9am	Milk	D								
2. 3	Normanton											
	SHUNT (Pass)								D			
	Normanton	5.37	Pass	D								
6.38	Sowerby Bge.	7.29	Pass	SX								
6.38	Sowerby Bdge.	7.20	Pass	SO								
7.53	Mirfield								SX			
7.43	Mirfield								SO			
	RELIEF 7.53am by Turn 52			SX								
	7.43am by Turn 53			SO								

MIRFIELD LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCHESTER. SHEET 79".

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINEMEN'S WORKINGS ONLY

MIRFIELD - SHEET 9.

					Book	Book		
					<u>On</u>	<u>Off</u>	<u>H.</u>	<u>M.</u>
					a.m.	p.m.		
Turn 52					6.18	1.54	7.36	SX
<u>PREPARE ENGINE FOR: Turn No: Leaves Shed:</u>								
7.40am Headfield Jn. 41 7. 3am 'S'								
RELIEVE 7.29am from Sowerby Bdge. SX								
Turn 51 at 7.53am								
Mirfield 7.54am Pass SX (2)								
8.28am	Normanton	9. 0	LE	SX				
9.13	Wakefield Shed							
RE-COAL SX								
Wakefield Shed 10. 0 LE SX								
10. 5	Wakefield							
SHUNT Pass to 12.30pm SX								
Wakefield 12.40 Pass SX								
12.54pm	Thornhill							
RELIEF 12.54pm by Turn 54 SX								
					a.m.	p.m.		
Turn 53					7.15	3.15	8. 0	SO
RELIEVE 7.20am from Sowerby Bridge SO								
Turn 51 at 7.43am								
Mirfield 7.44am Pass SO (2)								
8.15am	Normanton	9. 0	LE	SO				
9.13	Wakefield Shed							
RE-COAL SO								
Wakefield Shed 10. 0 LE SO								
10. 5	Wakefield							
SHUNT (Pass) to 10.45 SO								
Wakefield 10.53 Pass SO								
11.19	Barnsley	11.25	Pass	SO				
11.49	Wakefield	12.40pm	Pass	SO				
12.54pm	Thornhill							
RELIEF 12.54pm by Turn 55 SO								
<u>PREPARE ENGINE FOR: Turn No: Leaves Shed:</u>								
2.50pm LE to Headfield Jn 50 2.50pm 'S'								
4.30pm to Congleton 43 4.22pm 'S'								
					a.m.	p.m.		
Turn 54					11.41	7.29	7.48	SX
Mirfield 12. 9pm As Pass SX								
12.14pm	Thornhill							
RELIEVE 12.40pm ex Wakefield SX (2)								
Turn 52 at 12.54pm SX								
Thornhill 12.56 Pass SX								
1.26	Bradford	2. 5	LE Cpld	SX				
2.13	Low Moor	3. 3	Pass	SX				
3.10	Bradford	4.25	Pass	SX				
5.44	Holmfirth	6.25	LE	SX				
7.14	Shed							

MIRFIELD LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCHESTER. SHEET 80".

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINEMEN'S WORKINGS ONLY MIRFIELD - SHEET 10.

					Book On a.m.	Book Off p.m.	H. M.
Turn 55	Mirfield	12. 9pm	As Pass	SO	11.41	8.19	8.38 SO
12.14pm	Thornhill						
	RELIEVE	12.40pm	from Wakefield	SO			
	Turn 53 at	12.54pm					
	Thornhill	12.56	Pass	SO	(2)		
1.26	Bradford	2.55	Pass	SO			
4.24	Penistone	5.15	Pass	SO			
6.58	Bradford	7.38	LE	SO			
8. 4	Shed						

Turn 56

N O T U S E D

					a.m.	a.m.	
Turn 57					4.45	11.30	6.45 SX
	Shed	5.30am	LE	SX			
5.35am	Mirfield	6. 0	ES	SX	(9)		
6. 9	Headfield Jn.	7. 0	LE	SX			
7. 8	Thornhill	7.34	Pass	SX			
8. 2	Bradford	8.45(1)	LE	SX			
9.25	Mirfield						
	WORK AS REQUIRED			SX			
	Mirfield		LE	SX			
	Headfield Jn.	10.50	ES	SX			
11. 0	Mirfield		LE	SX			
11.15	Shed						
	(1) Coupled to Turn 46 & 47.						

Turn 58

N O T U S E D

Turn 59

N O T U S E D

MIRFIELD LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P'
MANCHESTER. SHEET 81".

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINEMEN'S WORKINGS ONLY

MIRFIELD - SHEET 11.

	Book	Book	
	On	Off	H. M.
	a.m.	p.m.	
Turn 60	5.30	2.18	8.48 SO

ENGINE PREPARED by Turn 260

	Shed	5.45am	LE	SO	
	Mirfield	6. 0	ES	SO	
6. 9am	Headfield Jn	7. 0	LE	SO	
7. 8	Thornhill	7.34	Pass	SO	(9)
8. 2	Bradford	8.25	ES	SO	
8.34	Low Moor	8.55	LE	SO	
9.17	Mirfield				
	SHUNT (Pass) to	11.30am			
	Mirfield	11.38	LE	SO	
11.48	Huddersfield	12.23pm	Pass	SO	
12.57pm	Clayton West	1.10	Pass	SO	
1.43	Huddersfield	1.53	LE	SO	
2. 3	Shed				

Turn 61					p.m.	p.m.	
					4. 0	11.45	7.45 SO
	Shed	4.45pm	LE	SO			
4.50pm	Mirfield	5.20	Pass	SO	(9)		
6. 9	Clayton West	6.37	Pass	SO			
7.25	Mirfield	7.29	ES	SO			
7.37	Headfield Jn.	7.50	LE	SO			
	Huddersfield	9.18	Pass	SO			
9.52	Clayton West	10.15	Pass	SO			
10.48	Huddersfield	11. 0	ES	SO			
11.10	Mirfield		LE	SO			
11.30	Shed						

Turn 62					a.m.	a.m.	
					3.35	9.27	5.52 SO
	Shed	4.20am	LE	SO			
4.25am	SHUNT (Pass) to	4.45am					
	Mirfield	5. 0	Pass	SO	(8)		
5.11	Huddersfield	5.50	Pass	SO			
6.18	Penistone	6.48	Pass	SO			
7.22	Huddersfield	7.42	Pass	SO			
8.12	Halifax	8.50	LE	SO			
9.12	Shed						

Turns 63 to 99

N O T U S E D

SHEETS 12 to 21.

N O T U S E D

MIRFIELD LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCHESTER. SHEET 82".