

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY

BOLTON - SHEET 1.

ONE CLASS 4 TANK (STD 2-6-4)

Turn 1

	Bolton	5.25am	Pass	SX	(100)
5.51am	Manchester	5.55	LE	SX	
6. 3	Red Bank	6.57	ES	SX	
7. 0	Manchester	7.10	Pass	SX	
8.30	Preston		LE	SX	
9.10	L.Hall Shed			SX	
	L.Hall Shed	3.15pm	LE	SX	(24C/154)
3.34pm	Preston	4. 0	Pass	SX	
5.32	Todmorden	6.18	Pass	SX	
7.12	Blackburn	7.25	LE	SX	
7.46	L.Hall Shed			SX	
	L.Hall Shed	9.35pm	LE	SX	(101)
	Preston	10.32	Pass	SX	
11.13pm	Bolton			SX	
	SHUNT (Pass) to 1. 0am			SX	
	Bolton	6.10am	Pass	SO	(102)
7. 5am	Accrington			SO	
	SHUNT (Pass) to 7.45			SO	
	Accrington	7.58	Pass	SO	
8.28	Bury B.St.	8.50	LE	SO	
9.35	Blackburn	11.50	Pass	SO	
12.25pm	Bolton			SO	

Turn 2.

N O T U S E D

Turn 3.

ONE CLASS 4 TANK (STD 2-6-4).

	Shed	5.40am	LE Cpld	SX	(106)
	Bolton			SX	
	SHUNT (Pass) to 7. 0			SX	
	Bolton	7.20	Pass	SX	
8.44am	Liverpool	9.25	ES	SX	(27A/106)
9.33	Kirkdale	9.49	ES	SX	
9.57	Liverpool	10.55	ES	SX	
11. 2	Kirkdale		LE	SX	
11.20	B.H.Shed			SX	
	B.H.Shed	4.10pm	LE	SX	(27A/152)
4.16pm	Liverpool	5.22	Pass	SX	
6. 9	Wigan			SX	
	SHUNT (Pass) to 8. 0			SX	
	Wigan	8.25	Pass	SX	
9.11	Liverpool	10.15	Pass	SX	(27A/153)
11.19	Bolton	11.30	LE	SX	
11.38	Shed				

/Contd...

BOLTON LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P'
MANCHESTER. SHEET 178."

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY

BURY - SHEET 1.

ONE CLASS 4 TANK (STD 2-6-4)

Turn 1.

	Shed	5. 0am	LE	SX	
	Rochdale	5.46	ES	SX	(15)
5.55am	Littleboro	6.20	Pass	SX	
6.56	Manchester	7.36	Pass	SX	
8.55	Bacup		LE	SX	
9.15	Bacup Shed			SX	
	Bacup Shed	4. 0pm	LE	SX	
	Bacup	4.40	Pass	SX	(30)
5.52pm	Manchester	6.33	Pass	SX	
6.58	Stalybridge	7.15	Pass	SX	
7.38	Manchester	8.25	Pass	SX	
8.58	Bury K.St. Shed		LE	SX	
	Shed	5. 0am	LE	SO	
	Rochdale	5.46	ES	SO	(16)
5.55am	Littleboro	6.20	Pass	SO	
6.56	Manchester	7.36	Pass	SO	
8.55	Bacup		LE	SO	
9.15	Bacup Shed			SO	
	COAL ENGINE				
	Bacup Shed	11.45am	LE	SO	
	Bacup	12.20pm	Pass	SO	(17)
1.40pm	Manchester	3.20	Pass	SO	
4. 5	Rochdale	4.58	Pass	SO	
5.24	Manchester		ES	SO	
	Irwell Bdge.			SO	
	Manchester	6.12	Cpld.	SO	
6.41	Bolton			SO	
	SHUNT (Pass) to	10.30		SO	
	Bolton	10.42	Pass	SO	
11.15	Rochdale	11.30	LE Cpld	SO	(23)
	Bury Shed				

BURY LOCO' to acknowledge receipt by wire to "DVL 'P' MANCHESTER.
SHEET 269".

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY.

BACUP - SHEET 1.

ONE CLASS 3 F (L & Y O-6-O)

Turn 1.

	Shed	6. 5am	LE	D	(82)
6.15am	Waterfoot			D	
	Shunt (Frt) and Test Vehicles			D	
	Waterfoot	7.35	LE	D	
7.40	Rawtenstall			D	
	SHUNT (Frt) and Test vehicles			D	
	Service Ashworths Coal Sidings			D	
	Rawtenstall	9.40	Frt	D	
9.48	Waterfoot			D	
	SHUNT Coal Sidings and prepare			D	
	Empties for 2.30pm (SX) Waterfoot			D	
	To Ramsbottom			D	
	Waterfoot	10.50	E&B	SX	
11. 0	Rawtenstall			SX	
	SHUNT (Frt) to	1.45pm		SX	
	Rawtenstall	1.45pm	LE	SX	
2. 3pm	Bacup Shed			SX	
	Waterfoot	10.50	TF	SO	
11. 0	Rawtenstall			SO	
	SHUNT (Frt) 11. 0 to	1.10pm		SO	
	Rawtenstall	1.12pm	LE	SO	
1.30pm	Bacup Shed				
	Bacup	3.54pm	Pass	SX	(50)
4.30	Bury K.St.		LE	SX	
	Bury B.St.	5.48	Pass	SX	(8)
6.24	Bacup		LE	SX	
6.45	Bacup Shed				

Turn 2.

CLASS 2P TANK (L & Y).

	Bacup	2.20pm	Pass	SO	(26D/21)
2.56pm	Bury B.St.				
	SHUNT (Pass) to	4.40pm		SO	
	Bury B.St.	4.57	Pass	SO	
5.37	Bacup	6.30	Pass	SO	(43)
7. 4	Bury B.St.	8.20	Pass	SO	
8.57	Bacup	9.40	Pass	SO	
10.17	Bury K.St.	10.37	Pass	SO	
11.17	Bacup				

Turns 3 to 6.

N O T U S E D

BACUP LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCR.
SHEET 258."

PASSENGER ENGINE WORKINGS COMMENCING 8TH JUNE, 1953.

ENGINE WORKINGS ONLY

LEES - SHEET 1.

ONE CLASS 3 TANK (STD 2-6-2)

Turn 1

	Shed	5.35am	LE Cpld	SX	(30)
5.59am	Stalybridge			SX	
	SHUNT (Pass)			SX	
	Stalybridge	6.45	Pass	SX	
8.23	Leeds C.S.	9.35	ES	SX	
10.23(A)	Gledholt Jn.	10.47	LE	SX	(A) Arrives 10.44amFO
10.53	Huddersfield Shed			SX	
	Huddersfield	4.31pm	Pass	SX	(31)
6. 6pm	Stockport	6.47	Pass	SX	
7.14	Stalybridge	7.25	LE	SX	
7.44	Lees Shed				
	Shed	6.55am	LE	SO	
7. 5am	Greenfield	7.40	Pass	SO	(72)
8.32	Stockport			SO	
	SHUNT (Pass & Frt)			SO	
	Stockport	12.27pm	Pass	SO	(57)
12.54pm	Stalybridge	2.30	Pass	SO	
2.45	Stockport			SO	
	SHUNT (Pass)			SO	
	Stockport	6. 2	Pass	SO	
6.32	Clegg St.	6.55	ES	SO	
7. 0	Lees		LE	SO	
7.15	Shed			SO	

ONE CLASS 4 TANK (STD 2-6-4)

Turn 2.

	Shed (6.10H)	6.23am	LE	SX	
6.28am	Lees	6.43	Pass	SX	(34)
7.25	Stockport	7.55	Pass	SX	(Bunker first)
8.26	Manchester V	9.35	Pass	SX	
10. 0	Mumps		LE	SX	
	Shed			SX	
	Shed	4.10pm	LE	SX	
4.15pm	Clegg St.	4.52	Pass	SX	(36)
6.31	Leeds C.S.			SX	
	Work as required			SX	
	Leeds C.S.	8.45	Fish	SX	
10.56	Manchester Ex	11.15	LE	SX	
11.50	Lees Shed			SX	
	Shed (6.10H)	6.23am	LE	SO	
6.28am	Lees	6.43	Pass	SO	(35)
7.25	Stockport	7.55(1)	Pass	SO	(Bunker first)
8.26	Manchester V.	9.10	Pass	SO	(1) Work 7.55am to
9.56	Rochdale	12.15pm	Pass	SO	Mancr. Saturdays
12.35pm	Mumps		LE	SO	13th June, also
1. 5	Shed			SO	12th & 19th Sept.
					To be LE 7.36am
					Stockport to Mancr
					on Sats.20th June
					to 5th Sept.

LEES LOCO' to acknowledge receipt by wire to "DIVISIONAL 'P' MANCHESTER.
SHEET 299".

PASSENGER ENGINE WORKINGS COMMENCING 8th JUNE, 1953.

ENGINE WORKINGS ONLY. BELLE VUE - SHEET 1.

Turn 1.

CLASS 5 (STD 2-6-0).
20th June to 19th September

	Shed	5.15am	LE	SO	
5.37am	Red Bank	6.10	ES	SO	
6.13	Manchester	6.45	Pass	SO	(14)
8.57	Blackpool N.	10.25	Pass	SO	(15C/368) (17A/200.218)
4.32pm	Leicester		ES	SO	
5. 0	Queniborough				
(Balanced by 15C engine 5.45am Desford - Blackpool (N))					

Turn 2. CLASS 5 (STD 2-6-0).
20th June to 19th September

	Shed	3.40am	LE	SO	
4. 6am	Red Bank	4.50	ES	SO	
4.54	Manchester	5.20	Pass	SO	(12)
5.48	Bolton	6.13	Pass	SO	
7. 1	Preston	7. 8	LE	SO	
7.45	Blackpool N.	9.35	Pass	SO	(24E) (19A) (16A)
2.17pm	Nottingham	2.25pm	ES	SO	
2.32	Edwalton	-	LE	SO	
-	Nottingham Shed				
(Balanced by Nottingham engine off 7.28am Nottingham to Blackpool N.)					

Turn 3. CLASS 5 (STD 2-6-0).
1st to 22nd August.

	Shed	3.40am	LE Cpld.	SO	
4. 6am	Red Bank	4.50	ES Cpld.	SO	
4.54	Manchester	5.20	Cpld.	SO	(10)
5.48	Bolton	6.13	Cpld.	SO	
7. 1	Preston	7. 8	LE Cpld.	SO	
7.45	Blackpool N.	8.55	Pass	SO	(10) (19A/39)
11.58	Sheffield	12.13pm	ES	SO	
12.37pm	Unstone C.S.	1. 5	LE	SO	
1.38	Sheffield Shed				