

(SECTION H)

BRITISH RAILWAYS

LONDON MIDLAND OPERATING AREA

(CENTRAL DIVISION).

This Time Table must be kept strictly private and must not be given to the public.

WORKING TIME TABLE

OF

FREIGHT TRAINS

FLEETWOOD, BLACKPOOL (TALBOT RD., CENTRAL) AND BOLTON AND CLIFTON JUNCTION, AND BRANCHES.

21st SEPTEMBER, 1953, until further notice.

EXPLANATION OF REFERENCES.

- | | | |
|--|--|--|
| <p>Q.....Runs when required.
 M X...Mondays excepted.
 M O...Mondays only.
 MSX..Mondays and Saturdays excepted.
 T X...Tuesdays excepted.
 T O...Tuesdays only.
 W X...Wednesdays excepted.
 W O...Wednesdays only.
 Th X..Thursdays excepted.
 Th O..Thursdays only.</p> | <p>F X....Fridays excepted.
 F O....Fridays only.
 S X....Saturdays excepted.
 S O....Saturdays only.
 C L....Coast Line.
 MR...Marton Line.
 A Arrive.
 B Attach or detach bank engine.
 D Depart.
 E Time allowed for examination.</p> | <p>l Stops only to change engines or trainmen.
 R Reverse.
 V Stops for traffic purposes if required.
 W Engine booked to take water.
 X Stops to apply or release wagon brakes.
 * Stops to shunt for or follow other trains.</p> |
|--|--|--|

When the arrival and departure of trains are not both stated, the time shown is the departure time.

* Notes to trains so marked in the heading appear at the foot of the page.

Passing times at places where trains run from slow or goods to fast or main lines are shown	10.20
Passing times at places where trains run from fast or main to slow or goods lines are shown	10.20
Starting or stopping times on main or fast lines are shown	10.20
Starting or stopping times on slow or goods lines are shown	10.20
Passing times on main or fast lines are shown	10.20
Passing times on slow or goods lines are shown	10.20

INDEX TO THE TABLES.

	Pages
Fleetwood and Blackpool (Talbot Road and Central) to Clifton Junction (including Horwich Branch and Horwich Fork Junction to Crow Nest Junction and Dobbs Brow Junction)	2—17
Clifton Junction to Blackpool (Central and Talbot Road) and Fleetwood (including Dobbs Brow Junction and Crow Nest Junction to Horwich Fork Junction and Horwich Branch)	18—30
Shunting Engines	31

Miles.	For continuation of trains from junction see page	Classification	WEEKDAYS										
			K	G	H		H	H	H	H	H	J	
			11.40 p.m. Preston Dock to Bamber Bridge.	Light Engine.	Empties		11.18 p.m. Blackburn to Moston.	12.50 a.m. Aldershot Sidings to Healey Mills.	12.28 a.m. Wigan to Bury (Knowlsey St.).	To Euxton Coal Sidings.	10.40 p.m. Hellfield to Heaton Mersey.	10.10 p.m. from Rose Grove.	
		Control Reporting Number.	P9				41			42	132		
			MX a.m.	MX a.m.	MX a.m.		MX a.m.	MO a.m.	MX a.m.	MX a.m.	MX a.m.	MX a.m.	
0		WYRE DOCK SIDINGS ..dep.	1										
		Wyre Dock Junction	2										
1 1/4		Burn Naze Sidings	3										
	 { arr.	4										
3		Thornton	5										
	 { dep.	6										
4 1/4		Poulton No. 5	7										
	 { arr.	8										
0		BLACKPOOL (Talbot Rd.) dep.	9										
1		Layton	10							1 13			
	 { arr.	11										
2 1/2		Poulton { No. 4	12										
	 { arr.	13										
3 1/2	 { dep.	14							1 22			
0		BLACKPOOL (Central) dep.	15										
		" (South) ..dep.	16										
4		ST. ANNES	17										
	 { dep.	18										
7 1/2		Lytham Goods Junction { arr.	19										
	 { dep.	20										
11 9 1/2		Kirkham North Junction	21			12 07				1 37			
	 { arr.	22										
11 1/2		Kirkham Station	23										
	 { dep.	24										
14 1/2		Salwick	25										
	 { arr.	26			12 24				1 57			
19		PRESTON { No. 5	27										
	 { arr.	28										
19 1/2	 { dep.	29										
		Ribble Sidings	30										
19 1/2	 { arr.	31			12 47							
	 { dep.	32										
22		Farington Curve Junction	33										
	 { arr.	34										
25		Farington Junction	35										
	 { dep.	36										
25 1/2		Euxton Junction	37										
	 { arr.	38										
26 1/2		Euxton (R.O.F.) Sidings ..	39										
	 { dep.	40										
28 1/2		Euxton No. 1	41										
	 pass	42										
30 1/2		Chorley	43										
	 { arr.	44										
30 1/2	 { dep.	45										
		Adlington Junction	46										
	 { arr.	47										
31 1/2	 { dep.	48										
		Grindford Bar Sidings.....	49										
	 { arr.	50										
	 { dep.	51										
33		Blackrod Junction	52										
	 { arr.	53										
	 { dep.	54										
33 1/2		Horwich Loco. Junction ..dep.	55										
	 { arr.	56										
	 { dep.	57										
		Horwich	58										
	 { arr.	59										
	 { dep.	60										
		Horwich Loco. Junction { arr.	61										
	 { dep.	62										
33 1/2	 { arr.	63										
	 { dep.	64										
34 1/2		Horwich Fork Junction ..	65										
	 pass	66										
		Hindley & B. B. Junction ..pass	67										
	 pass	68										
34 1/2		Dobbs Brow Junction	69										
	 pass	70										
37		Crow Nest Junction	71										
	 pass	72										
37		Lostock Junction	73										
	 { arr.	74										
	 { dep.	75										
39 1/2		Bullfield	76										
	 { arr.	77										
39 1/2		Bolton West	78										
	 { dep.	79										
40		BOLTON (East Junction) ..	80										
	 { arr.	81										
	 { dep.	82										
40 1/2		Burnden Junction	83										
	 { arr.	84										
	 { dep.	85										
41 1/2		Moses Gate.....	86										
	 { arr.	87										
	 { dep.	88										
43		Linnshaw Moss.....	89										
	 { arr.	90										
	 { dep.	91										
44 1/2		Kearsley Junction	92										
	 { arr.	93										
	 { dep.	94										
44 1/2		Robin Hood Sidings	95										
	 { arr.	96										
	 { dep.	97										
45 1/2		Pepper Hill Sidings	98										
	 { arr.	99										
	 { dep.	100										
45 1/2		CLIFTON JUNCTION.....	101										
	 { arr.	102										
	 { dep.	103										