

For the information and guidance of
Railway Officers and Railway Staff only.

No. 1

BRITISH RAILWAYS

NORTH EASTERN REGION

**YORK STATION
TRAIN WORKING**

**8th June to 20th September
inclusive, 1953**

**Station Master's Office
YORK**

**H. GARDNER
Station Master**

June, 1953

ARRIVALS AND DEPARTURES—WEEKDAYS—continued.

WTT No.	From	Down		Plat- form	Up		To	Remarks	Engine Working	Set Working
		Arr.	Dep.		Arr.	Dep.				
230	York	..	a.m.	2	a.m.	6 40	Normanton ..	To Blackpool (Cen.) on Sats. 11th July to 22nd August	Ex Shed	10-5 p.m. Scarborough SX 6th July to 11th Sept. 11-58 a.m. Don- caster MX other dates 3-37 a.m. Leeds, Sats 18th July to 22nd Aug. Made up LMR set, 11th July.
251	Niddrie	UM	pass	6 51	Whitemoor ..	Braked
1000	Selby	..	7 13	8	7 15		Rowntree's Halt	SX	Through	Through.
1000	Selby	..	7 13	9	7 15		York ..	SO	12-42 p.m. Selby	12-42 p.m. Selby.
2838	York	13	7 15		Harrogate	Ex Shed	12-47 a.m. Normanton MX , 12-19 a.m. Normanton Suns.
281	York	1 SX 10 SO	7 20		Sheffield Mid.	4-43 a.m. Sheffield MSX , Ex Shed MSO	8-1 p.m. Sheffield Mid. previous weekday. 1-50 a.m. Bristol Sats. 8-28 p.m. Sheffield (Sat. set).
3070	York	..	7 24	2 L.E.'s	7 25		Scarboro' Shed	SO Not after 12th Sept.	7-20 a.m. Cpld. ex Shed	
2763	Rowntree's Halt	..	7 24	8 N	7 30		York ..	SX E.C.S. ..	8-22 a.m. Doncaster ..	12-33 p.m. E.C.S., to Selby FO , 5-0 p.m. E.C.S. FSX Rown- tree's Halt.
2711	York	2	7 30		Leeds	Ex Shed	See C.W.21 for previous work- ing. (Attach CK, 3 TK SO).
3076	York	..	7 40	2 L.E.'s	7 41		Scarborough Shed	SO 20th June to 5th Sept.	7-35 a.m. cpld. engines ex Shed	
5401	York	3	7 45		Doncaster	Ex Shed	6-14 p.m. Doncaster previous weekday.

ARRIVALS AND DEPARTURES—WEEKDAYS—continued.

WTT No.	From	Down		Plat- form	Up		To	Remarks	Engine Working	Set Working
		Arr.	Dep.		Arr.	Dep.				
2581	York	a.m. 7 53	6	a.m.	Hull	Ex Shed	..	6-57 p.m. Leeds previous week-day.
—	York-Shed	..	L.E.	pass 8 2	Dringhouses	8-40 a.m. Heaton
13	Darlington	..	8S	8 7	Doncaster	To Shed. Selby	7-13 a.m.	Through.
2765	Scarborough	..	8N	8 9	Leeds	Through	..	Through.
2813	Harrogate	..	13	8 12	York	..	Shunts own train to Clifton C.S.	9-40 a.m. Skipton 10-12 a.m. Harrogate	SO SX	12-20 p.m. Harrogate p.m. Harrogate SO .
2708	Normanton	..	14	8 13	York	..	Shunt to No. 7 Clifton C.S. by train (engine)	10-10 a.m. Manchester	..	8-50 a.m. Scarborough to 18th Sept., 9-43 a.m. Scarborough SX , 29th June to 3rd July, 7-30 a.m. Leeds (see C.W.21 for dates), forms 2-7 a.m. Normanton Suns. , 12th July to 23rd Aug. (Detach C.W.283 Sats.).
2710	Bradford, F Sq via Leeds	8 20	9	8 20	York	10-15 a.m. F. Sq.	Bradford,	10-15 a.m. Bradford, F. Sq.
18	York	..	16	8 20	Edinburgh	Ex Shed
520	King's Cross	..	DM	pass 8 23	Heaton	..	Braked	SO Parcels. Attach BTK
2558	Hull	..	8S	8 24	York	..	Pilots at Station, (Shunts own train to Old Station daily)	To Shed	..	5-14 a.m. Leeds SX , 10-44 a.m. Leeds SO . (Detach T, SX).
5400	Doncaster	..	15	8 26	York	12-5 p.m. Doncaster	..	Part 12-5 p.m. Doncaster